

Factory
3200 Sixth Avenue South • Seattle, Washington
TWX 910-444-2095
Telex: 32-0318 FAX: (206) 382-7346

Mailing Address: P.O. Box 3546 • Seattle, Washington 98124 Telephone: (206) 623-5800

July 23, 1993

Ms. Christie True Metro Industrial Waste Section Senior Industrial Waste Investigator 130 Nickerson Street Suite #200 Seattle, WA. 98109-1658

Dear Ms. True:

Enclosed is the results for our composite sample of July 9, 1993. As you can see our Zinc levels were high, after investigating the situation we found some galvanized nuts & bolts in the process system. The system was shut down and cleaned, and all maintenance employees & passivation crew members were reminded of the importance of good house keeping in all areas. I feel this was an isolated incident and should not be a problem in the future.

Sincerely,

ALASKAN COPPER WORKS

Gerald A. Thompson Environmental Assistant

## FRIEDMAN & BRUYA, INC.

## **ENVIRONMENTAL CHEMISTS**

Date of Report: July 15, 1993 Date Received: July 9, 1993

Project: 7238, Metro Self Monitor, PO #M 29801

Date Samples Extracted: July 13, 1993 Date Extracts Analyzed: July 13, 1993

## RESULTS FROM THE ANALYSIS OF THE WATER SAMPLE FOR CHROMIUM, COPPER, NICKEL AND ZINC Samples Processed Using Method 3005 Results Reported as mg/L (ppm)

Sample ID	<b>Chromium</b>	Copper	<u>Nickel</u>	Zinc
M 29801	1.9	1.1	3.7	3.9
Quality Assurance				
Blank	< 0.05	< 0.05	< 0.05	<0.05
M 29801 (Duplicate)	1.9	1.2	3.8	3.9
M 29801 (Matrix Spike) % Recovery	108%	99%	110%	120%
M 29801 (Matrix Spike Duplicate) % Recovery	109%	97%	110%	120%
Spike Blank % Recovery	105%	100%	105%	108%
Spike Level	5	5	10	5